

Test Report

No. : CE/2008/B3270 Date : 2008/11/20 Page : 1 of 3


CNBSOLUTIONS LIMITED
ROOM 301, 3RD FLOOR, TECHNOLOGY BUILDING NO. 3 JIAN YE LU, JIDA,
ZHUHAI GUANGDONG CHINA



The following sample(s) was/were submitted and identified by/on behalf of the client as :

Sample Description : MINERAL WOOL BLANKET
Buyer : WOOL FACTORY
Supplier : SHANGHAI ADVANCED BUILDING MATERIALS MINERAL
SGS Ref. No. : GZ11424382EC
Sample Receiving Date : 2008/11/13
Testing Period : 2008/11/13 TO 2008/11/20

=====
Test Result(s) : Please refer to next page(s).


Chenyu Kung / Operation Manager
Signed for and on behalf of
SGS TAIWAN LTD.
Chemical Laboratory – Taipei

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company.
除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部分複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Test Report

No. : CE/2008/B3270 Date : 2008/11/20 Page : 2 of 3

CNBSOLUTIONS LIMITED
ROOM 301, 3RD FLOOR, TECHNOLOGY BUILDING NO. 3 JIAN YE LU, JIDA,
ZHUHAI GUANGDONG CHINA



Test Result(s)

PART NAME NO.1 : YELLOW MINERAL WOOL BLANKET

Test Item (s):	Unit	Method	MDL	Result
				No.1
Lead (Pb)	mg/kg	With reference to IEC 62321/2nd CDV (111/95/CDV). Determination of Lead by ICP-AES.	2	n.d.
Asbestos	---	---	---	---
Actinolite (CAS No.: 013768-00-8)	%	As per NIOSH 9000 method. Analysis was performed by XRD.	1	Negative
Amosite (CAS No.: 012172-73-5)	%	As per NIOSH 9000 method. Analysis was performed by XRD.	1	Negative
Chrysotile (CAS No.: 012001-29-5)	%	As per NIOSH 9000 method. Analysis was performed by XRD.	1	Negative
Crocidolite (CAS No.: 012001-28-4)	%	As per NIOSH 9000 method. Analysis was performed by XRD.	1	Negative
Tremolite (CAS No.: 014567-73-8)	%	As per NIOSH 9000 method. Analysis was performed by XRD.	1	Negative
Anthophyllite (CAS No.: 017068-78-9)	%	As per NIOSH 9000 method. Analysis was performed by XRD.	1	Negative

- Note :
1. mg/kg = ppm ; 0.1wt% = 1000ppm
 2. n.d. = Not Detected
 3. MDL = Method Detection Limit
 4. "---" = Not Conducted


Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company.
除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部分複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Test Report

No. : CE/2008/B3270 Date : 2008/11/20 Page : 3 of 3

CNBSOLUTIONS LIMITED
ROOM 301, 3RD FLOOR, TECHNOLOGY BUILDING NO. 3 JIAN YE LU, JIDA,
ZHUHAI GUANGDONG CHINA



** End of Report **

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company.
除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部分複製。

This Test Report is issued by the Company under its General Conditions of Service printed overleaf or available on request and accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this Test Report is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.